

WELL CONSTRUCTOR'S REPORT


WISCONSIN STATE BOARD OF HEALTH

Wel 6

1. COUNTY Ozaukee		CHECK ONE <input checked="" type="checkbox"/> Town <input type="checkbox"/> Village <input type="checkbox"/> City		NAME Cedarburg	
2. LOCATION (Number and Street or 1/4 section, section, township and range Also give subdivision name, lot and block numbers when available.) NE, S.E. 1/4 Of Sec. 28 T-10-N R-21-E					
3. OWNER AT TIME OF DRILLING L.A. Rice					
4. OWNER'S COMPLETE MAIL ADDRESS Williams Drive R.R. 2 Cedarburg, Wis. 53012					
5. Distance in feet from well to nearest: (Record answer in appropriate block)		BUILDING C. I.	SANITARY SEWER C. I.	FLOOR DRAIN C. I.	FOUNDATION DRAIN SEWER CONNECTED INDEPENDENT
		17	30	25	17
CLEAR WATER DRAIN C. I.	SEPTIC TANK TILE	PRIVY	SEEPAGE PIT	ABSORPTION FIELD	BARN SILO ABANDONED WELL SINK HOLE
17	50			55	
OTHER POLLUTION SOURCES (Give description such as dump, quarry, drainage well, stream, pond, lake, etc.)					

6. Well is intended to supply water for:

Home

7. DRILLHOLE						10. FORMATIONS		
Dia. (in.)	From (ft.)	To (ft.)	Dia. (in.)	From (ft.)	To (ft.)	Kind	From (ft.)	To (ft.)
10	Surface	22	6	110	151	Clay	Surface	20
6 1/2	22	110				Hard Pan	20	65
8. CASING, LINER, CURBING, AND SCREEN						Sand		
Dia. (in.)	Kind and Weight	From (ft.)	To (ft.)	Soft Sandstone			65	105
6 1/2	Per foot 26# casing	Surface	110	Loose Rock			105	110
7" od.	new, black steel			Sand Stone (water bearing)			110	151
	casing							
9. GROUT OR OTHER SEALING MATERIAL								
Kind	From (ft.)	To (ft.)						
Clay slurry	Surface	22						

11. MISCELLANEOUS DATA				Well construction completed on Nov. 8th 19 66	
Yield test: 5	Hrs. at 15	GPM	Well is terminated 10 inches <input checked="" type="checkbox"/> above <input type="checkbox"/> below final grade		
Depth from surface to normal water level 40 ft.			Well disinfected upon completion <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Depth to water level when pumping 50 ft.			Well sealed watertight upon completion <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Water sample sent to Madison			laboratory on: Nov. 8th 19 66		

Your opinion concerning other pollution hazards, information concerning difficulties encountered, and data relating to nearby wells, screens, seals, type of casing joints, method of finishing the well, amount of cement used in grouting, blasting, sub-surface pumprooms, access pits, etc., should be given on reverse side.

SIGNATURE Howard Groth		COMPLETE MAIL ADDRESS 813 No. 3rd Ave. Cedarburg, Wis. 53012	
Please do not write in space below			

COLIFORM TEST RESULT cc: M.E. Ostrom	GAS — 24 HRS. 1/19/67	GAS — 48 HRS. Samples of cuttings to be submitted by the driller	CONFIRMED See letter driller's file 12/19/66	REMARKS
--	---------------------------------	--	--	---------